Doc W 1 UN408



ARMORED MEDICAL RESEARCH LABORATORY

FORT KNOX, KENTUCKY

INDEXED

PROJECT NO. 5 - CREW FATIGUE RESEARCH

Report On

Sub-Project No. 5-1, Adequate Head Room in Tanks



Project No. 5-1

November 27, 1942

W6 P3 V.7568

MAR AR 9A9r

ARMORED FORCE MEDICAL RESEARCH LABORATORY Office of the Commanding Officer Fort Knox, Kentucky

Project No. P5-1 File No. 741-3 470.8

November 27, 1942

ADEQUATE HEAD ROOM IN TANKS

- 1. PROJECT: Adequate Head Room in Tanks.
- a. Authority Letter, Commanding General, Headquarters Armored Force, Fort Knox, Kentucky, 400.112/6 GNOHD, dated September 24, 1942.
- b. Purpose To determine the sitting heights of Armored Force personnel and to compare these with existing head clearances in tanks. Sitting posture is a significant factor in fatigue.

2. DISCUSSION:

- a. The sitting heights of 541 men from the 1st Battalion, Armored Force Replacement Training Center were measured with the men sitting erect on a flat table. Attached histogram (inclusions I & II) gives the actual distribution. Statistical analysis shows this group to be an adequate sample from which to draw conclusions.
- b. The thickness of the crash helmet at the vertex was determined and found to vary, depending upon the helmet design, from one-half $(\frac{1}{2})$ to one and one-half $(\frac{1}{2})$ inches.
- c. The maximal distance between the cushion of tank seats and the overhead closed hatch or armor plate has been called net head room. See attached inclusion III.
- d. The height of each man is increased by the distance from the top of his head to the top of his helmet. There is a slight and variable compression of the seat cushions. There is an indeterminate stoop in each individual which will tend to decrease the space needed for him. However, he must sit nearly erect to operate his periscope efficiently. The vertical adjustability of the periscope is small, the range of men's heights relatively larger; therefore, vertical seat mobility should be such as to make it possible for all sizes of men to adjust themselves comfortably to their periscopes and still not be touching the roof of the tank.

431988

Office of the Commanding Officer Fort Ener, Kentucky

Project No. 75-1 Pile No. 761-3 470.8

HOADSPUL SE' THIS

ADMIN'T HEAD ROOM IN TANKS.

I. PROJECT: Adequate Head Room in Tunks.

Force, Mort thex, Mentucky, A00,112/6 GRUHD, debut September 21, 1942.

b. Thereas - To detarmine the sitting head clearences in banks, personnel and to compare those with eximiting head clearences in banks, nixting posture is a significant factor in fatigue.

2, Discossion:

The eliting heights of SAI men from the lat Sattalion, Armored Force Replacement Training Center mere measured with the men mitting erent on a Clat table. Attached mistogram (inclusions I t II) gives the actual distribution, otatistical ensiyes shows this group to be an adequate cample from which to draw conclusions.

b. The thickness of the crash helpet at the vertex ass determined and found to very, depending upon the beliest design, from one-helf (2) to one and one-helf (1) inches.

The maximal clatance between the cushion of tank seats and the everyond classed hatch or armor plate has been called net head room. See extached inclusion III.

The height of such tab is increased by the distance from the way of his need to the tab of his helpht. There is a slight and variable crayrestion of the seat combions. There is an indeterminate about in each individual which will tend to decrease the space needed for him. However, he such mit will needly erect in operate his periacope efficiently. The vertical adjustability of the periacope is mail, the range of men's heights relatively larger; there fore, vertical enat mobility should be such as to make it possible for all sizes of men to adjust themselves confortably to their periacopes and still not be bouching the reaf of the tank.

3. CONCLUSIONS:

- a. The range of sitting heights of 541 soldiers taken at random from the Armored Force Replacement Training Center, 1st Battalion, is from 322 inches to 40-3/4 inches.
 - b. The mean sitting height is 36 ± 0.866 inches.
- c. Approximately one and one-half (l_2^1) inches is added to this height in each instance by the crash helmet.
- d. Inclusion IV shows the available seat space in the driver's compartment of the M-5 light tank. It has been determined that the tank can be driven satisfactorily if the maximum required head room is made available. A major change in seat design is necessary to effect this change. Inclusion IV also indicates the position and height adjustability required in such a redesigned seat.
- e. Improper seat heights result in cramped positions, increased fatigue and decrease the combat efficiency of men.
- f. Inclusion VII shows the per cent of men accommodated by varying degrees of head clearance both with and without crash helmets of la" thickness. Recent reports indicate that the helmet is perhaps unnecessary. The Armored Force Board is testing a helmet of considerably less thickness.
- g. An 8" adjustment is required to cover the total range of subjects in either the high or the low position, with or without helmet.
 - h. Forward and backward adjustment should be retained.
- i. The feature of a two-position change is good since it requires a minimum of time in changing from the "open" to the "buttoned up" position. Additional adjustment to fit the individual is also required.
- j. Since the high and low ranges overlap (see inclusion IV) it might be possible to install an adjusting arrangement similar to that in the turret seats of the new M-5 light tanks which moves thru the total range by small increments.

4. RECOMMENDATIONS:

- a. These basic data be passed on to the Division of Tank Design, and Ordnance Department, with the recommendation that proper seat heights be provided in all future models.
- b. That tank manufacturers be requested through proper channels to provide adequate clearance for men in the seats of new tanks now in production.

De CONCTOSTORS:

- g. The range of sixting heights of 541 soluters taken at range from the Armored Force Replacement Training Center, lat Settalion, is from 52% inches to 40-3/4 inches.
- b. The mean stating Asignt to 30 % 0,800 inches.
- c. Approximately one and one-half (11) inches is added to this height in each instance by the cresh heimst.
- d. Inclusion IV shows the available seat space in the driver's conpartment of the M-5 light tank. It has been determined that the tank can be driven estimizatorily if the maximum required head room is made available. A major change in seat design is necessary to effect this change, inclusion IV also indicates the position and height adjustability required in such a redesigned sent.
- fatigue and decrease the combat efficiency of sen,
- Inclusion VII shows the par cent of men accommodated by verying degrees of head classance both with and without crash beliefs of law thickness. Mosent reports indicate that the belief is perhaps undecomment. The stranged force Board is testing a belief of considerably less thickness.
- g. An 8" adjustment is required to cover the total range of subjects in alther the high or the low position, with or without belast.
- h. Forward and backward adjustment should be retained.
- L. The feature of a two-position change to good since it requires a minimum of time in changing from the Moreum to the Mostkoned up" position. Additional adjustment to fit the individual is also required.
- 2. Since the high and low ranges overlap (see inclusion IV) it alght be possible to install an adjusting arrangement similar to that in the turret scate of the new N-5 light tanks which moves thru the total range ty small increments.

" BECOM BELLVILLORS

- A. These basic data be passed on to the Division of Tank Besign, and Ordnance Department, with the recommendation that proper seat heights be provided in all future models.
- b. That tank manufacturers be requested through proper channels to provide adequate plearance for men in the seats of new tanks now in production.

- c. That the degree of elevation and lowering of the seats be related to the known facts about the sitting heights of men here included.
- d. That tank seat design be facilitated by excluding from all future tank crews the upper and lower 5% of men. The resultant acceptable range of sitting heights then becomes 34" to 38½". The exclusion of 10% of men results in diminishing the requirement for seat vertical adjustability at either the high or low position of 50%.
- e. Recommend that the Division of Tank Design, Ordnance Department, and the Armored Force Medical Research Laboratory collaborate in the design of proper seats to replace those which do not permit adequate headroom in existing tanks. It is apparent that such an alteration cannot readily be made in the field and the practicability of making a substitute seat should be seriously considered.

7 Inclusions

Reported by:

Captain W. F. Ashe Captain L. B. Roberts Major E. A. Blair

APPROVED Willard Maclile
WILLARD MACHIE.

Lt. Col., Medical Corps Director of Research

That the degree of elevation and lowering of the seate be related to the boom facts should the sitting heights of new here included.

d. That tank seat design be facilitated by excluding from all fulure tank order the upper and homer 5% of men. The resultant acceptable range of sitting beights then becomes 3% to 38%. The exclusion of 10% of men results in diminishing the requirement for sext wereless adjustability at either the high or low position of 50%.

E. Becommend that the Division of Tank Design, Ordinance Department, and the Armered Forms Medical Messeron Laboratory collaborate in the design of proper seats to replace those which do not permit adequate beadroom in existing tanks. It is apparent that such an alteration cannot readily be made in the field and the practicability of making a substitute seat should be seriously considered.


A TRETTHEOUR

Reported by:

Captain E. F. Rebarts Captain I. B. Rebarts Estir E. A. Mair WINDOWS Willerd Stackle

Lt. Col., Medical Corps Director of Research

DISTRIBUTION OF SITTING HEIGHTS OF MEN



I MCLUSTON II

Sitting Height Data


Inches	Number of Men	% of Total	Percentile Distribution
321	1	0.18	0.18
32_3/1.	2	0.37	0.55
33 33½ 33½ 33–3/4 34 34½	4	0.74	1.29
334	3	0.55	1.84
332	5	0.92	2.76
33-3/4	4 3 5 7 8	1.29	2.05
34		1.48	5.53
344	11	2.02	7.55
345	19	3.52	11.07
34-3/4	22	4.06	15.13
35 35 35 35 2	28	5.18	20.31
354	33	6.10	26.41
35-3/4	39	7.20	33.61
25-2/4	47	8.69	42.30
36 362 362	33 48	6.10	48.40
364	14	8.87	57.27
36-3/4	38	8.13 7.03	65.40
37	23	4.25	72.43
37 37½ 37½	27	4.99	76.68 81.67
374	24	4.44	86.11
37-3/4	24	Li . lili	90.55
38	20	3.69	94.24
381	7	1.29	95.53
38½ 38½		1.48	97.01
38-3/4	8 8	1.48	98.49
39 39 39 39	2	0.37	98.86
394	2 2	0.37	99.23
392	1 0	0.18	99.41
39-3/4		0	//
40	0	C	
402	0 2	0	
402	2	0.37	99.78
40-3/4	1 541	0.18	99.96
TOTAL	541	99.96	



INCLUSION III

NET HEAD ROOM

Position	M - 5 Light	M-4 A-2 Medium	N-4 A-3 Medium	M-4 A-4 Nedium
Driver - Lowered	35½	36½	37½	35-7/8
Ass't. Oriver - Low	351	36	36-5/8	361
Tank Comd'r Low	34	40-3/8	40-3/4	404
Gunner - Lowered		37-3/4	404	37½
Gunner - Raised		341/4	404	34
Leader		352	34-7/8-381	35½
Leader - Lowered	33½			
Loader - Raised	25			



High adjusting region Low adjusting region Ton ficon INCLUSION IF



